



SI B 66 05 07  
Distance Systems, Cruise Control, Remote Control

October 2007  
Technical Service

---

## SUBJECT

### Paint Peeling from PDC Sensor

## MODEL

E70 (X5), E83 (X3) vehicles produced September 1, 2006 to February 22, 2007

## SITUATION

Paint partly or fully peels from the PDC (Park Distance Control) sensors. In the case of partial paint peeling or blistering, this may interfere with the operation of the PDC system.

Part numbers affected:

- ┆ 66 20 9 127 800
- ┆ 66 20 9 127 801

## CAUSE

Faulty painting process of PDC sensor. Stocks were cleared August 2007

## CORRECTION

In case of a customer complaint, replace all the PDC sensors on the affected bumper.

## PARTS INFORMATION

Part Number	Description	Quantity
Refer to EPC	PDC sensor	4

## WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle Limited Warranty.

Please refer to the latest KSD for all applicable labor operations and allowances.

If the appropriate labor operation is not contained in KSD, then a work time labor operation should be used.

<b>Defect Code</b>	<b>66 20 07 78 00</b>
--------------------	-----------------------

[ Copyright © 2007 BMW of North America, LLC ]